

# THE NEW HYDRO-FORCE REVOLUTION™ INJECTION SPRAYER



## AS12R Revolution Low-Pressure Hydro-Force Trouble Shooting Guide

### PROBLEM: WILL NOT DRAW CHEMICAL


CAUSES	PART	SOLUTIONS
Inlet Strainer Clogged	NA0803	Clean or Replace
Outlet Strainer Clogged	NA0825	Replace
Wrong Teejet Size	B012	Replace
Acorn Strainer Clogged	NA0840	Clean or Replace
Water Nozzle Clogged or Worn	NA0808	Clean or Replace Injector Valve
Needs Rebuild	NA0841	Install Kit
Bad Injector Valve	NA0852A	Replace
Chemical Build-up Inside of Valve	NA0852A	Clean Thoroughly with Vinegar

### PROBLEM: CONTAINER BACKFILLS


CAUSES	PART	SOLUTIONS
Injector Valve Needs Rebuild	NA0841	Install Kit
Bad Injector Valve	NA0850A	Replace

### PROBLEM: DOES NOT SHUT OFF OR LEAKS FROM GUN

CAUSES	PART	SOLUTIONS
Worn Gun	NA0820A	Replace
Valve Needs Rebuild	NA0842	Rebuild
Worn Valve in Gun	NA0845	Replace



## AS12R LP Injection Sprayer Wand



AS30 - 5Qt  
Container w/cap

